

# Inspection Photos

API: 055-06196

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/6/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/6/2023

## Inspection Photos



**Photo 1.** 2022 Drone aerial photo facing north along the former access road. The road was not recontoured and reclaimed but continues on past the location. Location shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/6/2023

## Inspection Photos



**Photo 2.** 2022 drone aerial photo. Facing southwest toward the location which was not recontoured and reclaimed. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/6/2023

## Inspection Photos



**Photo 3.** 2022 drone aerial photo Facing northeast toward the location. The location is not recontoured and reclaimed. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/6/2023

## Inspection Photos



**Photo 4.** Facing northwest toward the location. The location is not recontoured and reclaimed. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/6/2023

## Inspection Photos



**Photo 5.** Facing northwest toward the cut slope of the location.



## Inspection Photos



**Photo 6.** Facing east toward the fill slope of the location. There are noxious weeds along the fill slope such as field bind weed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/6/2023

## Inspection Photos



**Photo 7.** Facing northeast at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/6/2023