



Photo #1 Work over rig on Spicer Annex.

**Inspection Photos
Spill # 484557
Inspection
Date:5/31/2023**

**All Photos taken
by Kris Neidel**





Inspection Photos
Spill # 484557
Inspection
Date:5/31/2023

All Photos taken
by Kris Neidel

Photo #2 Open top tank part of rig crew. This tank was the source of this spill. Free fluid was removed from pad surface. NO soil has been removed. At the time of inspection, the well was flowing back to open top tank, staff did not approach the rig crew with the well flowing to the tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Spill # 484557
Inspection
Date:5/31/2023

All Photos taken
by Kris Neidel

Photo #3 Shale bin on location on west side of location. What is this? Soil appeared dry, no pooled fluid.





Photo #4 Stormwater gate, in closed position.

**Inspection Photos
Spill # 484557
Inspection
Date:5/31/2023**

**All Photos taken
by Kris Neidel**





Inspection Photos
Spill # 484557
Inspection
Date:5/31/2023

All Photos taken
by Kris Neidel

Photo #5 stormwater discharge.





Photo #6 Staining on pad near shale bin, in background.

Inspection Photos
Spill # 484557
Inspection
Date:5/31/2023

All Photos taken
by Kris Neidel





Inspection Photos
Spill # 484557
Inspection
Date:5/31/2023

All Photos taken
by Kris Neidel

Photo #7 staining on pad. This area was observed on previous inspections, this area was used for the road around the drill pad, lon south side of pad



Inspection Photos
Spill # 484557
Inspection
Date:5/31/2023

All Photos taken
by Kris Neidel

Photo #8 open top tank to left of photo. Rig pump in foreground.





Inspection Photos
Spill # 484557
Inspection
Date:5/31/2023

All Photos taken
by Kris Neidel

Photo #9 looking at open-top tank looking northwest





Inspection Photos
Spill # 484557
Inspection
Date:5/31/2023

All Photos taken
by Kris Neidel

Photo #10 stained soil around tank is remnant of spill.