

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2023

Submitted Date:

06/09/2023

Document Number:

712700239

FIELD INSPECTION FORMLoc ID 334276 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216172	WELL	PR	12/22/1990	CBM	067-07778	NEIL 34-13 1	PR
285294	WELL	PR		CBM	067-09187	NEIL 34-13 3	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank label not legible. See Photo #4.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	08/09/2023
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Present

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	cattle panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	cattle panel		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Diamond mesh		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	cattle panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	cattle panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 2		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		

Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	2" line from wellhead to separator.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Positioned on the 34-13 #1 wellhead.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Positioned on the 34-13 #3 wellhead.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	2" from separator to meterhouse. Meters not calibrated within one year		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	OTHER		37.187310,-107.665610
Comment:	Partially buried steel tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

AirsID

Wells Served By Facilities Above		API Number		AirsID	
API Number					
067-09187					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:			Date:		
Flaring:					
Type					
Comment:					
Corrective Action:			Date:		

Inspected FacilitiesFacility ID: 216172 Type: WELL API Number: 067-07778 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 06/13/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 285294 Type: WELL API Number: 067-09187 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 06/20/2022 Annual Brhd Completed? Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Gravel	Pass			
Gravel	Pass	Culverts	Pass			
Rip Rap	Pass					

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700244	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6141153