

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/08/2023

Submitted Date:

06/09/2023

Document Number:

712700240

**FIELD INSPECTION FORM**

Loc ID 326332 Inspector Name: Pattillo, Curtis On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone | Email                         | Comment                            |
|------------------|-------|-------------------------------|------------------------------------|
| Labowskie, Steve |       | steve.labowskie@state.co.us   |                                    |
| , General        |       | sjninspections@ikavenergy.com | <a href="#">All SW Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 216245      | WELL | PR     | 03/01/2020  | CBM        | 067-07851 | COGBURN A 1   | PR          |

**General Comment:**

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                          |       |  |
|--------------------|--------------------------|-------|--|
| Type               | PUMP JACK                |       |  |
| Comment:           | Square mesh              |       |  |
| Corrective Action: |                          | Date: |  |
| Type               | SEPARATOR                |       |  |
| Comment:           | Cattle panel             |       |  |
| Corrective Action: |                          | Date: |  |
| Type               | WELLHEAD                 |       |  |
| Comment:           | Cattle panel             |       |  |
| Corrective Action: |                          | Date: |  |
| Type               | OTHER                    |       |  |
| Comment:           | Telemetry, Cattle panel. |       |  |
| Corrective Action: |                          | Date: |  |

**Equipment:**

| Type               |                                     | #   | corrective date |
|--------------------|-------------------------------------|-----|-----------------|
| Bradenhead         |                                     | # 1 |                 |
| Comment:           |                                     |     |                 |
| Corrective Action: |                                     |     | Date:           |
| Flow Line          |                                     | # 1 |                 |
| Comment:           | 2" line from wellhead to separator. |     |                 |
| Corrective Action: |                                     |     | Date:           |
| Pump Jack          |                                     | # 1 |                 |
| Comment:           |                                     |     |                 |
| Corrective Action: |                                     |     | Date:           |
| Bird Protectors    |                                     | # 1 |                 |

|                                 |                   |  |       |
|---------------------------------|-------------------|--|-------|
| Comment:                        |                   |  |       |
| Corrective Action:              |                   |  | Date: |
| Type: Vertical Heated Separator | # 1               |  |       |
| Comment:                        |                   |  |       |
| Corrective Action:              |                   |  | Date: |
| Type: Ancillary equipment       | # 1               |  |       |
| Comment:                        | Wellhead          |  |       |
| Corrective Action:              |                   |  | Date: |
| Type: Prime Mover               | # 1               |  |       |
| Comment:                        | natural gas motor |  |       |
| Corrective Action:              |                   |  | Date: |
| Type: Ancillary equipment       | # 2               |  |       |
| Comment:                        | Telemetry         |  |       |
| Corrective Action:              |                   |  | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**

Facility ID: 216245 Type: WELL API Number: 067-07851 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 06/13/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment                                      |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|--|
| Gravel           | Pass            | Gravel                  | Pass                  |  |                          |  |
| Berms            | Pass            |                         |                       |  |                          |  |
| Ditches          | Pass            |                         |                       |  |                          |  |
| Compaction       | Pass            | Culverts                | Pass                  | Material Handling And Spill Prevention | Pass                     | Lube oil container within spill containment. |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**      NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 712700245    | Well Location Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6141154">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6141154</a> |