

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/09/2023

Submitted Date:

06/09/2023

Document Number:

708900713

**FIELD INSPECTION FORM**

Loc ID 334676 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270418	WELL	SI	11/01/2022	GW	045-09549	SHAEFFER 12-13C (D13W)	SI
270423	WELL	SI	11/01/2022	GW	045-09553	SHAEFFER 14-1A (D13W)	SI
270424	WELL	SI	11/01/2022	GW	045-09552	PITMAN 13-5B(D13W)	SI

**General Comment:**

[COGCC Inspection Report Summary](#)  
On 06/09/2023 at approximately 09:25 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at CAERUS PICEANCE LLC D13W pad. Location # 334676 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas. While there, I observed contractors with heavy equipment doing excavation work in front of the separator units to replace some flowlines & welder also working on location. Please refer to Form 42 document # 403421313 for further information. All production equipment has been disconnected & wellheads appear to have been shut in & LOTO is in place.

BMP's were not in place around stockpiled soils when I arrived on location however I spoke with Mike Knox from Caerus on location. He stated that they had just started digging a little earlier in the day & assured me that by the end of the day they would have BMP's around any stockpiled soils on location & any open excavation areas would be fenced off for wildlife protection. I informed him I would be back in the near future to verify.

This is a summary of inspection report.

Shared facilities with location # 324263

**Location**

<b>Lease Road:</b>			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

<b>Emergency Contact Number:</b>	
Comment: <input type="text" value="911/970-285-2615"/>	
Corrective Action: <input type="text"/>	Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment: <a href="#">Welding truck</a>			
Corrective Action:			Date:
Type: Other	# 1		
Comment: <a href="#">Backhoe</a>			
Corrective Action:			Date:
Type: Other	# 1		
Comment: <a href="#">Excavator</a>			
Corrective Action:			Date:
Type: Other	# 1		
Comment: <a href="#">Compaction roller</a>			
Corrective Action:			Date:

<b>Venting:</b>	
Yes/No	NO
Comment:	
Corrective Action:	Date:

<b>Flaring:</b>	
Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 270418 Type: WELL API Number: 045-09549 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut in

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 270423 Type: WELL API Number: 045-09553 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut in

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 270424 Type: WELL API Number: 045-09552 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut in

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse in some areas
		Ditches				
		Culverts				
		Compaction				
Compaction						
		Gravel				Sparse

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>Observed contractors with heavy equipment doing excavation work in front of the separator units to replace some flowlines &amp; welder also working on location. Please refer to Form 42 document # 403421313 for further information.</p> <p>All production equipment has been disconnected &amp; wellheads appear to have been shut in &amp; LOTO is in place.</p> <p>BMP's were not in place around stockpiled soils when I arrived on location however I spoke with Mike Knox from Caerus on location. He stated that they had just started digging a little earlier in the day &amp; assured me that by the end of the day they would have BMP's around any stockpiled soils on location &amp; any open excavation areas would be fenced off for wildlife protection. I informed him I would be back in the near future to verify.</p> <p>Shared facilities with location # 324263</p>	smelserw	06/09/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900714	Inspection 708900713 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6142337">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6142337</a>
708900715	Inspection 708900713 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6142338">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6142338</a>