

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC D13 Pad**  
**Location #: 334565**



**Photo # 9945 From entrance to location**



**Photo # 9946 From entrance to location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC D13 Pad**  
**Location #: 334565**



**Photo # 9947 From entrance to location**



**Photo # 9948 Location**





**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC D13 Pad**  
**Location #: 334565**



**Photo # 9949 Location**



**Photo # 9950 Location**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC D13 Pad**  
**Location #: 334565**



**Photo # 9952 Location**



**Photo # 9957 Flowline heating insulation open ended**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC D13 Pad

Location #: 334565



Photo # 9963 Flowline heating insulation open ended



Photo # 9958 Stained gravel



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC D13 Pad**  
**Location #: 334565**



**Photo # 9959 Stained soils**



**Photo # 9960 Stained soils & gravel**