

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2023

Submitted Date:

06/10/2023

Document Number:

708900722**FIELD INSPECTION FORM**Loc ID 334565 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

27 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89052	WELL	PR	06/01/2019	GW	045-07382	PITMAN 13-6	PR
89053	WELL	PR	06/01/2019	GW	045-07383	PITMAN 13-3	PR
89054	WELL	PR	06/01/2019	GW	045-07384	SHAEFFER 12-13 (D13)	PR
89055	WELL	PR	06/01/2019	GW	045-07385	SHAEFFER 12-14	PR
211135	WELL	PR	09/14/2000	GW	045-06894	PITMAN 13-4	PR

General Comment:**COGCC Inspection Report Summary**

On 06/09/2023 at approximately 09:42 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at CAERUS PICEANCE LLC D13 pad.

Location # 334565 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Flowline heating insulation open ended with a CA date of 06/17/2023

2. Housekeeping - Stained soils & gravel with a CA date of 06/20/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Methanol tank		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-2615	
Corrective Action:		Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soils & gravel on location		
Corrective Action:	Remove and properly dispose of all stained soils and gravel.	Date:	06/20/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Flowline heating insulation open ended		
Corrective Action:	Operators will prevent & minimize adverse impacts to wildlife resources.	Date:	06/17/2023
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit midstream meter & meter house		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Pressure transducers located on all bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient				
Comment: Unlined containment						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment: Centralized containment						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient				
Comment: Unlined containment						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	89052	Type:	WELL	API Number:	045-07382	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	89053	Type:	WELL	API Number:	045-07383	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	89054	Type:	WELL	API Number:	045-07384	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	89055	Type:	WELL	API Number:	045-07385	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	211135	Type:	WELL	API Number:	045-06894	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Small areas of light compaction
				Material Handling And Spill Prevention		Chemical tank containment
Gravel						Sparse in areas
		Culverts				
		Compaction				
		Gravel				Sparse
		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Housekeeping & Equipment for observed compliance issues.	smelserw	06/10/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
708900723	Inspection 708900722 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6142447
708900724	Inspection 708900722 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6142448