

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2023

Submitted Date:

06/11/2023

Document Number:

708900735

FIELD INSPECTION FORMLoc ID 311564 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210881	WELL	PR	04/13/1990	GW	045-06639	CLOUGH 3-28	PR

General Comment:**COGCC Inspection Report Summary**

On 06/09/2023 at approximately 08:43 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC CLOUGH 3-28 pad.

Location # 311564 in Garfield County Colorado.

Please refer to Inspection 708900175 conducted on 03/28/2023, previous corrective action has not been completed.

Location is within High Priority Habitat area/Bald Eagle Roost site & is within close proximity to NSO/Density/Black Bear Habitat areas.

Location is approximately 215 yards from the Colorado River.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Meter calibration info not conspicuously posted with a CA date of 04/07/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Wellhead & meter house only, no other production equipment associated with this well.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	Meter house			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/970-285-9377			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Deadman # & Marked	# 2			corrective date
Comment:	Marked			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	Meter calibration info not conspicuously posted			
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.			Date: 04/07/2023
Type: Plunger Lift	# 0			
Comment:	Well not on plunger lift			
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: 210881	Type: WELL	API Number: 045-06639	Status: PR
Insp. Status: PR			
Producing Well			
Comment:	Producing, well not on plunger lift		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Compaction				
		Sediment Traps				
		Ditches				
		Rip Rap				
		Culverts				
		Gravel				Sparse in some areas
Compaction						

Comment: [Appears gravel has been added to location & a portion of the access road.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Equipment for observed compliance issue.	smelserw	06/11/2023
Wellhead & meter house only, no other production equipment associated with this well.		

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
708900736	Inspection 708900735 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6142729
708900737	Inspection 708900735 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6142730