

Inspection Photos

API: 055-06301

Operator: CAPTUREPOINT LLC

Inspection Date: 6/8/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 6/8/2023

Inspection Photos



Photo 2. Facing northeast at the Gas Plant. There are noxious weeds along the road that needs to be controlled. Red arrow → Diffuse knapweed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 6/8/2023

Inspection Photos



Photo 1. Facing west at the entrance of the Gas Plant. There are noxious weeds along the road that need to be controlled. Red arrow → Diffuse knapweed, Hoary crest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 6/8/2023

Inspection Photos



Photo 3. Close up view of Hoary crest and Diffuse knapweed found at the gas facility and wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 6/8/2023

Inspection Photos



Photo 4. Facing northwest along the road. There are noxious weeds along the road that need to be controlled. Red arrow → Musk thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 6/8/2023

Inspection Photos



Photo 5. Facing southwest along the access road. There are noxious weeds that need to be controlled. Red arrow → Mullein and Musk thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 6/8/2023

Inspection Photos



Photo 6. Facing north toward the location. Red arrow → Mullein Noxious weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 6/8/2023