

Inspection Photos

API: 055-06285

Operator: CAPTUREPOINT LLC

Inspection Date: 6/8/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 6/8/2023

Inspection Photos




Photo 1. Facing northwest toward the location. There are numerous noxious weeds at the location and some are wilted from recent weed control effort. Red arrow → Scotch thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 6/8/2023

Inspection Photos



Photo 2. There appears to have been control of some noxious weeds on location but there are some that were missed and a follow up treatment needs to be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 6/8/2023

Inspection Photos



Photo 3. Facing northwest toward the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 6/8/2023

Inspection Photos



Photo 4. Facing north at east side of the location.. There are numerous noxious weeds that have not been controlled with no sign of wilting.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 6/8/2023

Inspection Photos




Photo 5. Facing north at the northeast side of the location. There is patches of Hoary crest which is a List B noxious weed that needs to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 6/8/2023