

Inspection Photos

API: 055-06209

Operator: CAPTUREPOINT LLC

Inspection Date: 6/8/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06209 | Date: 6/8/2023

Inspection Photos



Photo 1. Facing south along the access road. There are noxious weeds along the road that need to be controlled. Red arrow → Scotch thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06209 | Date: 6/8/2023

Inspection Photos



Photo 2. Well sign does not reflect current Operator and needs to be updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06209 | Date: 6/8/2023

Inspection Photos



Photo 2. There are noxious weeds Hoary crest (Whit top) along the southeast side of the location that needs to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06209 | Date: 6/8/2023

Inspection Photos



Photo 4. Facing northwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06209 | Date: 6/8/2023