

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2023

Submitted Date:

06/12/2023

Document Number:

709700092

FIELD INSPECTION FORM

 Loc ID 319902 Inspector Name: Huck, Keith On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 74165
 Name of Operator: RENEGADE OIL & GAS COMPANY LLC
 Address: 6155 S MAIN STREET #225
 City: AURORA State: CO Zip: 80016
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Condill, J. B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Espinosa, Bill		billespinosa30@yahoo.com	Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201818	WELL	SI	12/01/2019	GW	001-07222	CHAMPLIN 248 AMOCO B 1	SI

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#			corrective date
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:		Date:		
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:		Date:		
Type: Pump Jack	# 1			
Comment:				
Corrective Action:		Date:		
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to surface			
Corrective Action:		Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	1	300 BBLs	STEEL AST		39.832127,-104.585507
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berm with production tank				
Corrective Action:				
Date:				

Wells Served By Facilities Above

AirsID

API Number
001-07222

API Number	AirsID
------------	--------

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
Date:		

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 201818 Type: WELL API Number: 001-07222 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action: Date:

COGCC Comments

Comment	User	Date
Routine Inspection	huckk	06/12/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709700093	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6143378