

Inspection Photos

Location Name: Anschutz State 5-62-26-25 SWNW

Location ID: 438941



Photo 1 – Generator



Photo 2 – Flare

Inspection Photos
Location Name: Anschutz State 5-62-26-25 SWNW
Location ID: 438941



Photo 3 – Production Equipment



Photo 4 – Production Equipment

Inspection Photos
Location Name: Anschutz State 5-62-26-25 SWNW
Location ID: 438941



Photo 5 – Separators



Photo 6 – Separator and VRT

Inspection Photos
Location Name: Anschutz State 5-62-26-25 SWNW
Location ID: 438941



Photo 7 – VRUs



Photo 8 – Production Equipment

Inspection Photos
Location Name: Anschutz State 5-62-26-25 SWNW
Location ID: 438941



Photo 9 – Tank Battery Signs

Photo 10 – Tank Battery

Inspection Photos
Location Name: Anschutz State 5-62-26-25 SWNW
Location ID: 438941



Photo 11 – LACTs




Photo 12 – Missing Capacity Label

Inspection Photos

Location Name: Anschutz State 5-62-26-25 SWNW

Location ID: 438941



Photo 13 – ECDs



Photo 14 – Missing Capacity Label

Inspection Photos

Location Name: Anschutz State 5-62-26-25 SWNW

Location ID: 438941



Photo 15 – Gas Lift Injection Meter House



Photo 16 – Wellheads