

Well Name: Carpenter 32-6-3 2/Carpenter 32-6-3 1S
Document Number: 712700091
Location ID 438700
Inspector: Curtis Pattillo
Installed wattles along eastern side of location berms must be maintained or removed. Previous inspection on 1/11/2022 required the installation of BMPs and spot seeding. The area has not been stabilized, reseeding as not been successful. Contact the SW Reclamation Specialist Ryan Costa regarding interim reclamation. See Photos #2 & #3.
Correction Action Due: 5/5/2023
Action Taken: Contacted SW Reclamation Specialist Ryan Costa regarding interim reclamation. Installed new wattles/repositioned existing wattles surrounding location. Seeded and mulched slopes.

