

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/12/2023

Submitted Date:

06/12/2023

Document Number:

712700253

**FIELD INSPECTION FORM**

Loc ID 325150 Inspector Name: Pattillo, Curtis On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10766  
Name of Operator: ARKOMA OPERATIONS LLC  
Address: 2121 S COLUMBIA AVE SUITE 101  
City: TULSA State: OK Zip: 74114

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone          | Email                       | Comment            |
|------------------|----------------|-----------------------------|--------------------|
| Price, Andrew    | (918) 260-8324 | aprice@arkomaops.com        | All SW Inspections |
| Labowskie, Steve |                | steve.labowskie@state.co.us |                    |
| , General        |                | SJBcompliance@arkomaops.com | All SW Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 214128      | WELL | PR     | 10/17/1958  | GW         | 067-05439 | HARMON MVRD UNIT 1 | PR          |

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type  |     |       | corrective date |
|---|-----|-------|-----------------|
| Type: Deadman # & Marked  | # 5 |       |                 |
| Comment:  |     |       |                 |
| Corrective Action:  |     | Date: |                 |
| Type: Bradenhead  | # 1 |       |                 |
| Comment:  |     |       |                 |
| Corrective Action:  |     | Date: |                 |
| Type: Ancillary equipment   | # 1 |       |                 |
| Comment: Wellhead   |     |       |                 |
| Corrective Action:  |     | Date: |                 |
| Type: Flow Line   | # 1 |       |                 |
| Comment: 2" line from wellhead to separator.                                  |     |       |                 |
| Corrective Action:  |     | Date: |                 |
| Type: Bird Protectors   | # 1 |       |                 |
| Comment:  |     |       |                 |
| Corrective Action:  |     | Date: |                 |
| Type: Gas Meter Run   | # 1 |       |                 |
| Comment: 2" line from separator to meterhouse.<br>Calibrated within one year. |     |       |                 |
| Corrective Action:  |     | Date: |                 |
| Type: Horizontal Heated Separator   | # 1 |       |                 |
| Comment:  |     |       |                 |

|                    |       |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

**Tanks and Berms:**

| Contents       | # | Capacity | Type     | Tank ID | SE GPS                |
|----------------|---|----------|----------|---------|-----------------------|
| PRODUCED WATER | 1 | <50 BBLs | Open Top |         | 37.108580,-107.746470 |

Comment: [Screened, open top steel tank.](#)

|                    |       |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |

Comment:

|                    |       |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

**Venting:**

|                    |    |  |       |  |
|--------------------|----|--|-------|--|
| Yes/No             | NO |  |       |  |
| Comment:           |    |  |       |  |
| Corrective Action: |    |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 214128 Type: WELL API Number: 067-05439 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Annual bradenhead test past due.

07/12/2023

Corrective Action: Perform annual bradenhead test and submit Form 17 per Rule 419.c.

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 712700258    | Well Location Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6144031">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6144031</a> |