


Storm Water Management and Erosion control
Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17
Location #: 322404



**Location Overview: Location is approximately
30 yards from Baldy Creek
Section/Township/Range: 17 7S90W**

Storm water Management and Erosion control
Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17
Location #: 322404



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17
Location #: 322404



Photo # 102 Lack of stabilization/compaction



Photo # 103 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17
Location #: 322404



**Photo # 106 Lack of stabilization/compaction/
Insufficient tracking BMP's**



**Photo # 107 Lack of stabilization/compaction/
Insufficient tracking BMP's**

Storm water Management and Erosion control
Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17
Location #: 322404



**Photo # 108 Lack of stabilization/compaction/
Insufficient tracking BMP's**



Photo # 110 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17
Location #: 322404



Photo # 111 Lack of stabilization/compaction



Photo # 112 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17
Location #: 322404



Photo # 114 Lack of stabilization/compaction



Photo # 115 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17
Location #: 322404



Photo # 116 Lack of stabilization/compaction



Photo # 118 Lack of stabilization/compaction