

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 87 From entrance to location



Photo # 88 From entrance to location

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 89 From entrance to location



Photo # 90 Location

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 91 Location



Photo # 92 Location

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 93 Location



Photo # 100 Location

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 104 Location



Photo # 138 Location

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 139 Location



Photo # 95 Weeds/undesirable plant species encroaching on equipment

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 98 Weeds/undesirable plant species encroaching on equipment



Photo # 122 Weeds/undesirable plant species encroaching on equipment

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 93 Weeds/undesirable plant species encroaching on equipment



Photo # 99 Debris

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 131 Debris



Photo # 132 Debris

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 109 Improperly marked deadman/anchor



Photo # 121 Open ended load lines

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 130 Tank label has incorrect information



Photo # 133 Stained soils & gravel

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 134 Stained soils & gravel



Photo # 136 Stained soils & gravel

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 137 Stained soils & gravel



Photo # 123 Secondary containment not sufficient to contain 110% of tank capacity spilled or released materials/containment needs maintenance.

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 126 Secondary containment not sufficient to contain 110% of tank capacity spilled or released materials/containment needs maintenance.



Photo # 128 Secondary containment not sufficient to contain 110% of tank capacity spilled or released materials/containment needs maintenance.