

**KT Resources LLC
Ant Hill Unit 30-42
Location #316154**



East side access road to location



West side access road to location

KT Resources LLC Ant Hill Unit 30-42 Location #316154



Tank battery signs



Debris

**KT Resources LLC
Ant Hill Unit 30-42
Location #316154**



Containment full



Faded and illegible label

KT Resources LLC
Ant Hill Unit 30-42
Location #316154



Leaking equipment and stained soil



No gas meter calibration visibly displayed

**KT Resources LLC
Ant Hill Unit 30-42
Location #316154**



Stained soil



Stained soil

**KT Resources LLC
Ant Hill Unit 30-42
Location #316154**



Erosion and soil migration leaving location



Erosion and soil migration leaving location

**KT Resources LLC
Ant Hill Unit 30-42
Location #316154**



Location entrance and view from Southeast corner



Location view from Northeast corner

**KT Resources LLC
Ant Hill Unit 30-42
Location #316154**



Location view from Northwest corner



Location entrance and view from Southwest corner