

**KT Resources LLC  
Ant Hill Unit Wyatt 31-12  
Location #445610**



**Access road to location**




**Entrance to location**



**KT Resources LLC  
Ant Hill Unit Wyatt 31-12  
Location #445610**



**Debris**



**Gas meter calibration not visibly displayed**



KT Resources LLC  
Ant Hill Unit Wyatt 31-12  
Location #445610



Debris



Tank battery signs



**KT Resources LLC  
Ant Hill Unit Wyatt 31-12  
Location #445610**



**Stained soil**



**Containment drain**



**KT Resources LLC  
Ant Hill Unit Wyatt 31-12  
Location #445610**



**Leaking containment**



**Erosion away from corner of containment**



**KT Resources LLC  
Ant Hill Unit Wyatt 31-12  
Location #445610**



**Soil migration on to location**



**Erosion and soil migration entering location**



**KT Resources LLC  
Ant Hill Unit Wyatt 31-12  
Location #445610**



**Vehicle tracking**



**Lack of staibilization**



**KT Resources LLC  
Ant Hill Unit Wyatt 31-12  
Location #445610**



**Location view from Southwest corner**



**Location view from Northwest corner**



**KT Resources LLC  
Ant Hill Unit Wyatt 31-12  
Location #445610**



**Location view from Northeast corner**



**Location view from Southeast corner**