

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HILTON /25-26D

Location ID: 413865



Photo #306 From entrance to location.



Photo #307 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HILTON /25-26D

Location ID: 413865



Photo #308 From entrance to location.



Photo #310 Chemical tank containment full of stormwater.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HILTON /25-26D

Location ID: 413865



Photo #311 Chemical tank containment full of stormwater.



Photo #312 Stained soils and gravel by wellhead.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HILTON /25-26D

Location ID: 413865



Photo #313 Secondary capacity reduced due to Stormwater.



Photo #315 Secondary capacity reduced due to Stormwater.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HILTON /25-26D

Location ID: 413865



Photo #317 Undesirable plant species in tank containment.



Photo #318 Undesirable plant species in tank containment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HILTON /25-26D

Location ID: 413865



Photo #324 Cata flow heater within 75 feet of tanks.



Photo #325 Cata flow heater within 75 feet of tanks.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HILTON /25-26D

Location ID: 413865



Photo #328 Calibration cards not conspicuously posted.



Photo #320 Multiple holes in secondary containment liner.

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC HILTON /25-26D
Location ID: 413865



Photo #321 Multiple holes in secondary containment liner.



Photo #322 Multiple holes in secondary containment liner.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HILTON /25-26D

Location ID: 413865



Photo #323 Loadline open ended and not capped.