

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2023

Submitted Date:

06/16/2023

Document Number:

690204332

**FIELD INSPECTION FORM**

Loc ID 333537 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10749  
 Name of Operator: SIMCOE LLC  
 Address: 1199 MAIN AVE SUITE 101  
 City: DURANGO State: CO Zip: 81301

**Findings:**

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                        | Comment |
|--------------|-------|------------------------------|---------|
| SIMCOE       |       | sjninspections@ikavenergy.co |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 215423      | WELL | PR     | 11/11/2015  | CBM        | 067-07028 | PETER PHILLIPS A 1 | RI          |

**General Comment:**

On 6/16/2023, Ryan Costa conducted a follow up location and stormwater management inspection. An inspection report will be issued to both Operators of the location. See attached photos and additional details within this report

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

WEEDS

Comment: There are noxious weeds along the access road that need to be controlled. Corrective action needs to be addressed immediately. CA date is observed date of issue.

Corrective Action: Comply with Rule 1003.f.

Date: 06/15/2023

Overall Good:

**Spills:**

Type

Area

Volume

Condensate

Tank

Comment: There is oil stained soils at the burried tank that need to be cleaned up. Stained soils were observed inside and outside of containment. Corrective action needs to be addressed immediately. CA date is observed date of issue.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 06/15/2023

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

| Contents           | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------|---------|--------|
|                    |   |          |      |         |        |
| Comment:           |   |          |      |         |        |
| Corrective Action: |   |          |      |         | Date:  |

Paint

Condition

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|---|----------|---------------------|---------------------|-------------|
|   |          |                     |                     |             |
| Comment: <span style="color: blue;">Secondary containment may not be adequate due to stained soils outside of containment.</span> |          |                     |                     |             |
| Corrective Action:  |          |                     |                     | Date:       |

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: There is vehicle rutting along the access road that needs to be repaired and stabilized. Previous corrective action has not been completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 05/05/2023

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 690204333    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6151315">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6151315</a> |