

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad**  
**Location #: 335550**



**Location Overview: Location is approximately 500 yards from  
Mamm Creek  
Section/Township/Range: 18 6S92W**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad**  
**Location #: 335550**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad**  
**Location #: 335550**



**Photo # 888 Chemical containment approximately 1/2 full  
Failure to maintain chemical BMP's**



**Photo # 900 Chemical containment approximately 1/2 full  
Failure to maintain chemical BMP's**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad**  
**Location #: 335550**



**Photo # 949 Lack of stabilization/compaction**



**Photo # 950 Lack of stabilization/compaction**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad**  
**Location #: 335550**



**Photo # 951 Lack of stabilization/compaction**

**Photo # 953 Lack of stabilization/compaction**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad**  
**Location #: 335550**



**Photo # 954 Lack of stabilization/compaction**

**Photo # 955 Lack of stabilization/compaction**

# Storm water Management and Erosion control

Location Name: DIXON A Pad

Location #: 335550



Photo # 956 Lack of stabilization/compaction

Photo # 959 Lack of stabilization/compaction

# Storm water Management and Erosion control

Location Name: DIXON A Pad

Location #: 335550



Photo # 961 Lack of stabilization/compaction

Photo # 962 Lack of stabilization/compaction