

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2023

Submitted Date:

06/12/2023

Document Number:

696305003

**FIELD INSPECTION FORM**Loc ID 424271 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                    | Comment                         |
|--------------|-------|--------------------------|---------------------------------|
| ,            |       | Regulatory@verdadoil.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 424272      | WELL | PR     | 10/01/2021  | OW         | 123-33959 | Ptasnik 30-44-9-59 | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |  |       |            |
|----------------------|--|-------|------------|
| <b>Signs/Marker:</b> |  |       |            |
| Type                 | WELLHEAD   |       |            |
| Comment:             | Adequate   |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | BATTERY  |       |            |
| Comment:             | Adequate   |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | TANK LABELS/PLACARDS   |       |            |
| Comment:             | Crude Oil Tank Labels have faded no longer visible; see photos |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.h.                        | Date: | 07/14/2023 |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |             |       |  |
|--------------------|-------------|-------|--|
| <b>Fencing/:</b>   |             |       |  |
| Type               | LOCATION    |       |  |
| Comment:           | Barbed Wire |       |  |
| Corrective Action: |             | Date: |  |

|                               |     |       |                 |
|-------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>             |     |       | corrective date |
| Type: Vertical Separator      | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Vertical Heater Treater | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Pig Station             | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Emission Control Device | # 2 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Bradenhead              | # 1 |       |                 |

|                     |                                  |  |       |  |
|---------------------|----------------------------------|--|-------|--|
| Comment:            | Appears to be plumbed to surface |  | Date: |  |
| Corrective Action:  |                                  |  | Date: |  |
| Type: Pump Jack     | # 1                              |  |       |  |
| Comment:            |                                  |  | Date: |  |
| Corrective Action:  |                                  |  | Date: |  |
| Type: Gas Meter Run | # 1                              |  |       |  |
| Comment:            |                                  |  | Date: |  |
| Corrective Action:  |                                  |  | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | 400 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
|                    |                                      |                     |                     |             |
| Comment:           | Shares berm with the Crude Oil Tanks |                     |                     |             |
| Corrective Action: |                                      |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 3 | 400 BBLS | STEEL AST |         | 40.714600,-104.011780 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|        |  |  |
|--------|--|--|
| Yes/No |  |  |
|--------|--|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 424272 | Type: | WELL | API Number: | 123-33959 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |       |      |             |           |         |    |               |    |
| Comment:             |        | PR    |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           |         |    | Date:         |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <a href="#">Routine Field Inspection. Tank Labels</a> | petrie | 06/12/2023 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403430877    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6143782">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6143782</a> |
| 696305004    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6143778">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6143778</a> |