

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2023

Submitted Date:

06/20/2023

Document Number:

699504829

FIELD INSPECTION FORMLoc ID 479194 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10243

Name of Operator: GMT EXPLORATION COMPANY LLC

Address: 4949 S NIAGARA ST SUITE 250

City: DENVER State: CO Zip: 80237

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Silver, Randy		randy.silver@state.co.us	
Cox, BJ	303-586-9274	bjcox@gmtexploration.com	
Blair, Max	720-862-4503	mblair@gmtexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480426	WELL	PR	09/01/2022	OW	039-06722	Irwin 6-65 23-11 10HN	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sellhead sign was not visible on wellhead during inspection		
Corrective Action:	Install/repair wellhead sign on wellhead	Date:	07/20/2023

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	Gas generator		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric / automation		

Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 480426 Type: WELL API Number: 039-06722 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 06/22/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: new yearly bradenhead test will be due by 6/22/23 to stay in compliance of COGCC annual bradenhead testing rules.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail					

Comment: [Location BMP appear to be failing to mitigate stormwater runoff. See pictures](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 07/04/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 6/15/23 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Irwin 6-65 23-11 10HN</p> <p>Company Name- GMT Exploration Company LLC</p> <p>API- 05-039-06722</p> <p>In Elbert County Colorado.</p> <p>While there, I observed PR well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Location BMP appear to be failing to mitigate stormwater runoff. See pictures</p> <p>Install or repair required BMPs per Rule 1002.f.(2)C 7/4/23</p> <p>Wellhead sign was not visible on wellhead</p> <p>Install/repair wellhead sign on wellhead 7/20/23</p> <p>Annual bradenhead test will be due on 6/22/23 to stain in compliance according to COGCC annual bradenhead testing rules.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection weather conditions were overcast, warm, calm, recent rain.</p> <p>This is a summary of inspection report.</p>	medinaj	06/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504830	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6153685