

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2023

Submitted Date:

06/20/2023

Document Number:

699504831

FIELD INSPECTION FORMLoc ID 479191 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10243

Name of Operator: GMT EXPLORATION COMPANY LLC

Address: 4949 S NIAGARA ST SUITE 250

City: DENVER State: CO Zip: 80237

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Eberhardt, Whitney	303-586-9289	w.eberhardt@gmtexploration.com	Principal Agent
Cox, BJ	303-586-9274	bjcox@gmtexploration.com	
Burn, Diana		diana.burn@state.co.us	
Silver, Randy		randy.silver@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Blair, Max	720-862-4503	mblair@gmtexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480446	WELL	PR	11/10/2022	OW	039-06742	Crystal 6-65 22-10 10HN	PR

General Comment:

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wellhead sign not visible on wellhead during inspection		
Corrective Action:	Install/repair wellhead sign		Date: 07/20/2023

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: VRT	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	Gas lift		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric / automation		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	480446	Type:	WELL	API Number:	039-06742	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:			Annual Brhd Completed?	No					
Last Brhd Test Results	Initial Surf Csg Pressure:				Fluid Type:				
	End Surf Csg Pressure:								
Comment:	No bradenhead test on file, well is delinquent for bradenhead test. Well has shown production since 9/1/22. Contact COGCC engineering			06/20/2023					
Corrective Action:	Comply with COGCC annual bradenhead testing rules			Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail					

Comment: Stormwater BMP on location has failed, erosion and pooled stormwater was observed on location during inspection.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/05/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 6/15/23 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Crystal 6-65 22-10 10HN</p> <p>Company Name- GMT Exploration Company LLC</p> <p>API- 05-039-06742</p> <p>In Elbert County Colorado.</p> <p>While there, I observed PR well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stormwater BMP on location has failed, erosion and pooled stormwater was observed on location during inspection.</p> <p>Install or repair required BMPs per Rule 1002.f.(2)C 7/5/23</p> <p>Wellhead sign was not visible at time of inspection</p> <p>Install / repair wellhead sign 7/20/23</p> <p>No bradenhead test on file, well is delinquent for bradenhead test. Well has shown production since 9/1/22. Contact COGCC engineering</p> <p>Comply with COGCC annual bradenhead testing rules 6/20/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection weather conditions were overcast, warm, calm, recent rain.</p> <p>This is a summary of inspection report.</p>	medinaj	06/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504832	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6153686