

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2023

Submitted Date:

06/14/2023

Document Number:

712700263**FIELD INSPECTION FORM**Loc ID 326578 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258229	WELL	PR	02/24/2001	CBM	067-08339	ARGENTA 33-10 4-4	PR

**General Comment:**SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Road is steep and rutted, gravel is loose.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Present			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	CO-State B-listed musk thistle observed sporadically around the well location.			
Corrective Action:				Date:
Type	DEBRIS			
Comment:	Sbrubs observed growing immediately around the wellhead and pumpjack. See Photo #4.			
Corrective Action:	Rule 610. Implement actions to fully comply with Rule 610 regarding fire prevention and protection.			Date: 06/21/2023
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Welded angle iron.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Flow Line	# 2			corrective date
Comment:	2" line & 4" line from wellhead to separator.			
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:				

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	5" line from separator to meterhouse. Calibrated within one year.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gathering Line	# 1		
Comment:	Partially buried valve can.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	

**Venting:**

Yes/No	YES		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	258229	Type:	WELL	API Number:	067-08339	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	04/19/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Ditches	Fail			

Comment: [Observed erosion due to improper compaction on well location. See Photos #2 & #3.](#)  
[Observed erosion on access road. See Photo #5.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 06/28/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403433060	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6146213">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6146213</a>
712700268	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6146208">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6146208</a>