

Final Reclamation and Stormwater Inspection

Date: 06/14/2023

Operator: KLABZUBA OIL & GAS INC - 10148

Location ID: 393818

Inspection Document #: 708200322

Morgan County, CO

SWSW Section 29 T2N R57W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: AJU GLN-BDL-62N57W
Location ID: 393818




Photo 1. The access road (indicated by green lines) does not appear to have been re-contoured to reflect adjacent topography, indicated by red lines. Additional reclamation activities are required to come into compliance with Rule 1004.

Inspection Photos
Location Name: AJU GLN-BDL-62N57W
Location ID: 393818




Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: AJU GLN-BDL-62N57W
Location ID: 393818



Photo 2. The location does not appear to be progressing towards Rule 1004 standards. Staff observed that debris remains on location, the presence of undesirable vegetation (e.g. kochia and CO List C Noxious Weed-cheatgrass), and areas of exposed soil were observed throughout.

Inspection Photos
Location Name: AJU GLN-BDL-62N57W
Location ID: 393818



Photo 4. See comments in Photo 3.

Inspection Photos
Location Name: AJU GLN-BDL-62N57W
Location ID: 393818



Photo 5. See comments in Photo 3.



Photo 6. Close up of debris and undesirable vegetation (e.g. kochia).

Inspection Photos
Location Name: AJU GLN-BDL-62N57W
Location ID: 393818



Photo 7. Reference area photo taken west of location.