

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/22/2023

Submitted Date:

06/20/2023

Document Number:

701103747

FIELD INSPECTION FORMLoc ID 334296 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10453

Name of Operator: PARADOX UPSTREAM LLC

Address: 500 DALLAS ST SUITE #1650

City: HOUSTON State: TX Zip: 77002

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Rau, David	970-566-3151	dmrau@paragoncg.com	
Roberts, Jake	713.600.6219	jaker@paradoxresources.com	All Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265182	WELL	PR	09/01/2021	GW	113-06111	ANDY'S MESA FEDERAL 34	EG
271705	WELL	PR	10/01/2021	GW	113-06139	ANDY'S MESA FEDERAL 58	EG

General Comment:

Flowline integrity Inspection: tank integrity inspection

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	No label on buried tank.		
Corrective Action:	Label tank.	Date:	07/31/2023

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	WEEDS		
Comment:	See tank berm comments		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
	1	<100 BBLS	PBV STEEL		,	
Comment:	No label on tank. Tank is rusty.					
Corrective Action:						Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:										
Corrective Action:								Date:		
Contents		#	Capacity	Type		Tank ID	SE GPS			
PRODUCED WATER		2	400 BBLS	STEEL AST			,			
Comment:										
Corrective Action:								Date:		

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal				Inadequate	
Comment:	Grass growing inside of berm				
Corrective Action:	Maintain tank berm free of weeds.				Date: 07/31/2023

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 265182 Type: WELL API Number: 113-06111 Status: PR Insp. Status: EGFacility ID: 271705 Type: WELL API Number: 113-06139 Status: PR Insp. Status: EG**Flowline**#1 Type: Dump Line 4 of LinesFlowline DescriptionFlowline Type: Dump LineSize: 2"Material: Carbon Steel

Variance:

Age:

Contents:

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed:

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: 4 - 2" risers inside tank berm going to tanks.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103748	Inspection 701103747 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6156107