

Inspection Photos

Location Name: CAERUS PICEANCE LLC A29NE Pad

Location #: 335178



Photo # 1335 From entrance to location



Photo # 1336 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC A29NE Pad

Location #: 335178



Photo # 1337 Location



Photo # 1338 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC A29NE Pad

Location #: 335178



Photo # 1339 Location



Photo # 1344 Weeds/undesirable plant species around wellheads

Inspection Photos
Location Name: CAERUS PICEANCE LLC A29NE Pad
Location #: 335178



Photo # 1345 Weeds/undesirable plant species around wellheads



Photo # 1346 Weeds/undesirable plant species around wellheads

Inspection Photos

Location Name: CAERUS PICEANCE LLC A29NE Pad

Location #: 335178



Photo # 1357 Hole in secondary containment liner/liner needs maintenance



Photo # 1358 Hole in secondary containment liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC A29NE Pad

Location #: 335178



Photo # 1348 Weeds/undesirable plant species around wellheads