

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/15/2023

Submitted Date:

06/15/2023

Document Number:

708900775

**FIELD INSPECTION FORM**Loc ID 336015 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

24 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289851	WELL	PR	03/01/2023	GW	045-13885	ROBINSON A6	PR
289961	WELL	PR	03/01/2023	GW	045-13937	ROBINSON A5	PR
289962	WELL	PR	07/11/2013	GW	045-13936	ROBINSON A4	PR
289963	WELL	PR	03/30/2007	GW	045-13935	ROBINSON A3	PR

**General Comment:****COGCC Inspection Report Summary**

On 06/15/2023 at approximately 09:09 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC ROBINSON A Pad.

Location # 336015 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas.

Location is within a 411a Surface Water External Buffer &amp; approximately 642 yards from the Colorado River.

Location is within close proximity to National Wetlands Inventory area.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Meter calibration info not conspicuously posted with a CA date of 06/25/2023
2. Equipment - Unmarked deadman with a CA date of 06/29/2023
3. Stormwater - Berm needs maintenance with a CA date of 06/30/2023
4. Housekeeping - Unused equipment on location with a CA date of 06/30/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

## Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

## Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in secondary containment		
Corrective Action:	The storage of equipment not necessary for use on location is prohibited.		Date: 06/30/2023

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire		

Corrective Action:		Date:	
<b>Equipment:</b>		corrective date	
Type: Deadman # & Marked	# 2		
Comment:	1 marked deadman & 1 unmarked deadman		
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		Date: 06/29/2023
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 6		
Comment:	Meter calibration info not conspicuously posted		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.		Date: 06/25/2023
Type: Bradenhead	# 4		
Comment:	Pressure transducers & Taylor plugs on bradenheads, all bradenhead vales are accessible.		
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:		Centralized containment			
Corrective Action:		Date:			
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent		
Comment:					
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	HEATED STEEL AST		,
Comment:		Centralized containment			
Corrective Action:		Date:			
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent		
Comment:					
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	HEATED STEEL AST		,
Comment:		Centralized containment			
Corrective Action:		Date:			
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent		



Inspected Facilities				
Facility ID: 289851	Type: WELL	API Number: 045-13885	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:
Facility ID: 289961	Type: WELL	API Number: 045-13937	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:
Facility ID: 289962	Type: WELL	API Number: 045-13936	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:
Facility ID: 289963	Type: WELL	API Number: 045-13935	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms	Fail					Berm needs maintenance
		Culverts				
		Compaction				
Gravel						Sparse in areas
		Gravel				Sparse
Compaction						Small areas of light compaction

Comment: Berm needs maintenance - erosion through berm & transport of sediment off location (behind tank battery)

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 06/30/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<span style="color: blue;">Please refer to Housekeeping, Equipment &amp; Stormwater for observed compliance issues.</span>	smelserw	06/15/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403435810	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6150224">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6150224</a>
708900776	Inspection 708900775 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6150218">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6150218</a>
708900777	Inspection 708900775 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6150219">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6150219</a>