

Final Reclamation Inspection

June 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 323096

Inspection Document #: 701900895

SESW Section 21 T3N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096




Photo 1. 2021 aerial imagery of the well pad, tank battery and reference area. Note: well pad and tank battery shared a disturbance pad. Historical imagery confirms that the tank battery was on the southern end of the disturbance and has been completely absorbed by the new Kerr McGee production facility, location ID 464149.

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 2. Overview photo of the well pad taken at ground level from the southern edge facing north.

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096




Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing east. Note: well pad has a higher density of perennial grass cover compared to reference area which is dominated by cheatgrass (see photo #6).

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 5. Overview photo of the tank battery taken at ground level from the northern edge facing south. Note: tank battery disturbance has been absorbed my new active facility to the south.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number:
701900895

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 6. Well pad reference area to the north of the shared disturbance.