

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/24/2023

Submitted Date:

06/22/2023

Document Number:

701103750

FIELD INSPECTION FORMLoc ID 325606 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96735

Name of Operator: WILLIFORD RESOURCES LLC

Address: 6506 S LEWIS AVE STE 102

City: TULSA State: OK Zip: 74136

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stevens, Glenn		glennstevens@centurylink.com	All SW Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Williford, Hearne		hwilli@swbell.net	All SW field inspections
Devine, Ellice		ellice.devine@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215093	WELL	SI	02/01/2023	OW	067-06698	ANGELINA 4	EG

General Comment:

Flowline integrity inspection: Review of Form 44 (none found).

Flowlines not registered from wells (Angelina #4, 5, 6, 7, 8) to remote battery (Coordinates 37.1351 -108.09225) on County Road 129.

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Inspected Facilities

Facility ID: 215093 Type: WELL API Number: 067-06698 Status: SI Insp. Status: EG

Flowline

#1	Type:	of Lines
<u>Flowline Description</u>		
Flowline Type:	Size:	Material:
Variance:	Age:	Contents: <u>Crude Oil</u>
<u>Integrity Summary</u>		
Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:
<u>Pressure Testing</u>		
Witnessed:	Test Result:	Charted:
<u>COGCC Rules(check all that apply)</u>		
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment		
Comment:	Flowlines not registered from wells (Angelina #4, 5, 6, 7, 8) to remote battery (Coordinates 37.1351 -108.09225) on County Road 129.	
Corrective Action:	Submit an Eform 44 Flowline Report per Rule 1101.d.	
		Date: <u>07/28/2023</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103751	Flowline integrity inspection 701103750 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6158049
701103752	Map of Angelina #4, 5, 6, 7, 8 wells and remote battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6158050