

Inspection Photos
Location Name: CAERUS PICEANCE LLC A13W Pad
Location ID: 334564



Photo # 1444 From entrance to location



Photo # 1445 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC A13W Pad
Location ID: 334564



Photo # 1446 Location



Photo # 1447 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC A13W Pad
Location ID: 334564



Photo # 1448 Location



Photo # 1453 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC A13W Pad
Location ID: 334564



Photo # 1458 Debris



Photo # 1455 Unmarked deadman

Inspection Photos
Location Name: CAERUS PICEANCE LLC A13W Pad
Location ID: 334564



Photo # 1460 Hole in secondary containment liner/liner needs maintenance



Photo # 1461 Hole in secondary containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC A13W Pad
Location ID: 334564



Photo # 1463 Hole in secondary containment liner/liner needs maintenance



Photo # 1464 Hole in secondary containment liner/liner needs maintenance