

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2023

Submitted Date:

06/23/2023

Document Number:

707800423

**FIELD INSPECTION FORM**Loc ID 315693 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10384

Name of Operator: GENESIS GAS &amp; OIL COLORADO LLC

Address: 1141 NORTH LOOP 1604 E 105-414

City: SAN ANTONIO State: TX Zip: 78232

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

26 Number of Comments

15 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, COGCC		craig.burger@state.co.us	
, COGCC		shaun.kellerby@state.co.us	
,		dnr_cogccenforcement@state.co.us	COGCC Enforcement
Heil, John		john.heil@state.co.us	
Karcz, Jeffrey	(303) 909-6401	jkarcz@genesigoco.com	
, March Kimmel	210-363-2859	mkimmel@genesigoco.com	
, COGCC		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231362	WELL	SI	10/01/2022	OW	103-09032	MOORE 3-11 MH	PR

**General Comment:**

#### COGCC Inspection Report Summary

On Thursday 6/22/2023, I, Inspector Scott Ramsey, conducted a Follow up inspection at Genesis Moore 3-11MH, at Location # 315693 in Rio Blanco county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed well was producing. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.

All C/A's from previous inspection document's #700704423 and # 700704615 have not been completed. Therefore C/A dates remain the same. In addition strong odor of hydrocarbons was present. Production tank is open to atmosphere. FLIR video of venting is attached.

During this inspection the following compliance issues were observed:

1. Well head signage is lacking information. (C/A date 9/2/22)
2. No operator emergency number posted. 911 is posted. (C/A date 9/2/22)
3. Random staining (C/A date 8/12/22)
4. Random debris (C/A date 8/5/22)
5. Unused/stored equipment (C/A date 9/2/22)
6. Tank labels lacking information (C/A date 9/2/22)
7. Unlabeled open bucket with fluid in it. (C/A date 8/12/22)
8. Battery signage is incorrect (C/A date 9/2/22)
9. Weeds in containment (C/A date 10/28/22)
10. Open holes for wildlife to enter (C/A date 8/5/22)
11. Open pit behind tank not lined and no form 15 on file.
12. Drain on back of tank has been drained into undocumented, unlined earth pit.
13. Tank venting

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

## Location

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Battery sign has wrong information and no emergency contact numbers.		
Corrective Action:	Provide proper signage.	Date:	09/02/2022
Type	WELLHEAD		
Comment:	Well head signage is lacking information.		
Corrective Action:	Provide proper signage.	Date:	09/02/2022
Type	TANK LABELS/PLACARDS		
Comment:	Tank is lacking labeling.		
Corrective Action:	Provide proper labeling	Date:	09/02/2022

**Emergency Contact Number:**

Comment: None present

Corrective Action: Provide proper 24 hour operator contact number and/or local emergency contact.

Date: 09/02/2022

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	08/05/2022
Type	OTHER		
Comment:	Open holes for wildlife to enter.		
Corrective Action:	Eliminate possibility of wildlife to enter open lines/holes.	Date:	08/05/2022
Type	OTHER		
Comment:	Bucket with out labeling full of fluid at well head.		
Corrective Action:	Install proper labeling and secondary containment remove fluid.	Date:	08/12/2022
Type	OTHER		
Comment:	Random staining.		
Corrective Action:	Remove all impacted material and dispose of properly	Date:	08/12/2022
Type	STORAGE OF SUPL		
Comment:	Stored equipment.		
Corrective Action:	Remove all stored equipment not being used for operations.	Date:	09/02/2022
Type	WEEDS		
Comment:	Weeds in containment		
Corrective Action:	Remove weeds	Date:	10/28/2022
Type	OTHER		
Comment:	Electrical lines are all laying on the ground where wildlife could potentially be electrocuted.		
Corrective Action:	Eliminate possibility of wildlife being tangled in or electrocuted.	Date:	08/12/2022

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Crude Oil	Tank			
Comment:	Drain on back of tank has some fluid and crude oil drained into undocumented, unlined earth pit. Pumper on location explained in order to sell the oil he needed to drain the water off.			
Corrective Action:	Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff			Date: 06/26/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Barb wire in need of repair.		
Corrective Action:	Repair fencing to eliminate wildlife from entering		Date: 06/30/2023

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Well head		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	See stored equipment		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	See stored equipment		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1		STEEL AST		,
Comment:	Capacity unknown tank is not labeled. See signs/marker				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Not lined			
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	YES		
Comment:	Tank has a line on top of tank open to atmosphere. With strong petroleum odor. Took a FLIR video of venting. Open line on tank does have a valve or enardo.		
Corrective Action:	Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare.		Date: 10/21/2022

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	231362	Type:	WELL	API Number:	103-09032	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Well was producing at time of inspection.								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:

Lined: NO

Pit ID:

Lat:

Long:

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**Liner Type: OtherLiner Condition: Inadequate

Comment:

Pit is behind tank in secondary containment with a line from the tank to it. There is no form 15 on file.

Corrective Action

Submit an eForm 15 Pit Report to update COGCC records with current information to comply

Date:

12/01/2022**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

4 strand barb wire in need of repair

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

No netting present

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: Light Speed: \_\_\_\_\_ (mph) Direction From: \_\_\_\_\_ Weather: Partly Temperature: (F)Assisting Staff: Kirby Burchett Camera #: 3☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
11:30	AM	12:00	PM

Equipment
Oil Tank(s)
Wellhead(s)

Comment: See venting for C/ACorrective  
Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800424	OGI video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6159072">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6159072</a>
707800427	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6159073">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6159073</a>
707800428	OGI video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6159074">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6159074</a>