

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/23/2023

Submitted Date:

06/24/2023

Document Number:

707601416

**FIELD INSPECTION FORM**Loc ID 302381 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections
,		dnr_cogccengineering@state. co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298348	WELL	TA	05/04/2020	OW	123-29040	BUCKCHERRY USX AA 03 -12	PA

**General Comment:**

This is a PLUGGED & ABANDONED WELL inspection.  
 Well(s): 1: Plugged & Abandoned | PA.  
 Plugging Operations: Cementing: Surface plug.  
 Battery: Abandoned.  
 Abandoned Battery SE corner GPS coordinates: 40.519410 / -104.424290  
 Well GPS coordinates: 40.513539 / -104.429283

**Location****Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:		Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 298348 Type: WELL API Number: 123-29040 Status: TA Insp. Status: PA**Cement**Cement ContractorContractor Name: Axis Energy

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 6050'-2341'-0'Cement Volume (sx): 273 sxsGood Return During Job: YESCement Type: Class "G" Neat 15.8#Comment:

Workover Contractor: Axix Energy Services, Rig #716.  
Cement Contractor: Axix Energy Services.

## Reference:

Form 6N on file. Notice of Intent to Abandon date: 06/16/2023. Approved.

Form 42 on file. Notice of MIRU. Start Date: 06/20/2023. Approved.

Form 42 on file. Notice of Plugging Operations. Start Date: 06/20/2023. Approved.

2023/06/23:

Plugging Operations: Cementing: Surface plug.

2023/06/23: JSA attached as photo to this report.

CREW TRAVEL. HELD SAFETY MEETING. RU WIRELINE. SHOT HOLES AT 740'. RD WIRELINE. ROLLED HOLE WITH FRESH WATER. RD FLOOR. ND BOP'S. NU WELLHEAD. HELD SAFETY MEETING WITH AXIS CEMENT. RU CEMENT UNIT. PUMPED 10BBLS CHEM WASH FOLLOWED BY 5BBLS FRESH WATER. PUMPED 273 SACKS NEAT G. RD CEMENT UNIT. SHUT WELL IN. CLEANED TANKS. RD HARDLINE. RD SERVICE UNIT. LOCKED/TAGGED OUT WELL. SHUT DOWN.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On FRI 06/23/2023 at approximately 10:47 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: BUCKCHERRY USX AA-66N63W/3NWSW  Location ID: 302381  Well Name(s):  Buckcherry USX AA 03-12.  API: 123-29040.  Location County: Weld County, Colorado  Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed:  Well(s): 1: Plugged &amp; Abandoned   PA.  Plugging Operations: Cementing: Surface plug.  Battery: Abandoned.  Abandoned Battery SE corner GPS coordinates: 40.519410 / -104.424290  Well GPS coordinates: 40.513539 / -104.429283</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/24/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601417	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6159445">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6159445</a>