

Inspection Photos

Loc: 325172

Operator: LOGOS OPERATING LLC

Inspection Date: 6/15/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 6/15/2023

Inspection Photos



Photo 1. Facing southwest toward the access road. There are noxious weeds along the road that need to be controlled. Red arrow points to Musk thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 6/15/2023

Inspection Photos



Photo 2. Facing southwest toward the location and production equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 6/15/2023

Inspection Photos



Photo 3. Facing toward the open top tank. The secondary containment has been reinstalled into the ground. Larger rock rip/rap has been placed around the containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 6/15/2023

Inspection Photos



Photo 4. The secondary containment has been reinstalled into the ground. Larger rock rip/rap has been placed around the containment.



Photo 5. The lowest point of the containment sits approximately 1ft. 8 inches above ground level.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 6/15/2023

Inspection Photos



Photo 6. Facing toward the opposite side of the open top tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 6/15/2023

Inspection Photos



Photo 7. Facing toward the southwest side of the location. This area has been regraded and seeded. Most of the mulch has blown off and soils are not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 6/15/2023

Inspection Photos



Photo 8. Facing north along the the Florida River. There is no stormwater controls installed along the disturbed soils adjacent to the river which is a concern.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 6/15/2023

Inspection Photos



Photo 9. Facing north toward the location. The area of the road shows signs of scouring where flood flowed across the road from right to left towards the Florida River.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 6/15/2023

Inspection Photos



Photo 10. Facing south toward the location. The area of the road shows signs of scouring where flood flows across the road from left to right towards the Florida River. No BMPs have been installed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 6/15/2023