


Tiffany 5-2 and Tiffany 5-3
COGCC Inspection #690204125
Stormwater BMP Maintenance



Inspection photo 8. Sediment removed from and around straw bales. Complete 6/05/2023.



Inspection photo 9. BMPs in place to mitigate erosion. Completed 6/05/2023.



Inspection photo 4. Soil pile no longer present.



Inspection photo 10. Western swale rock check dams maintained; additional angular rip rap installed. Complete 6/05/2023.



Inspection photo 14. Rilling addressed and BMPs added at top of slope. Completed 6/05/2023.