

**Scout Energy Management LLC  
Associated Unit A 2X  
Location #316438**



**Vehicle tracking pad added since last inspection**



**Vehicle tracking pad added since last inspection**



# Scout Energy Management LLC Associated Unit A 2X Location #316438



**Wellhead sign, no tank battery on location**



**Surface casing plumbed into flowline**



**Scout Energy Management LLC  
Associated Unit A 2X  
Location #316438**



**Drainage repaired since last inspection**



**Drainage repaired since last inspection**



**Scout Energy Management LLC  
Associated Unit A 2X  
Location #316438**



**Sediment trap added since last inspection**



**Drainage repaired since last inspection**



**Scout Energy Management LLC  
Associated Unit A 2X  
Location #316438**



**Location view from Southeast corner**



**Location view from Northeast corner**



**Scout Energy Management LLC  
Associated Unit A 2X  
Location #316438**



**Location view from Northwest corner**



**Location view from Southwest corner**