

**Scout Energy Management LLC
McLaughlin 19
Location #311796**



Northwest entrance tracking pad installed since last inspection



East entrance tracking pad installed since last inspection

Scout Energy Management LLC
McLaughlin 19
Location #311796



South entrance tracking pad installed since last inspection



Well sign. No tank battery.



**Scout Energy Management LLC
McLaughlin 19
Location #311796**



Location view from Southeast corner



Location view from Northeast corner

**Scout Energy Management LLC
McLaughlin 19
Location #311796**



Location view from Northwest corner



Location view from Southwest corner