

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2023

Submitted Date:

06/28/2023

Document Number:

701103764

FIELD INSPECTION FORMLoc ID 333349 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dittrich, Wade	575-390-2828	Wade_Dittrich@Oxy.com	
Maestas, Eric	575-420-7825	eric_maestas@oxy.com	
Kosola, Jason		jason.kosola@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211800	WELL	PR	03/01/2017	CO2	055-06035	SHEEP MOUNTAIN UNIT 10-2	EG
211867	WELL	PR		CO2	055-06105	SHEEP MOUNTAIN UNIT 1 -1-J DRILL #5	EG
211868	WELL	PR	03/01/2021	CO2	055-06106	SHEEP MOUNTAIN UNIT 7 -35-L DRILL #5	EG

General Comment:

Flowline integrity inspection: CO2

Two unused flowline riser from wells (Sheep Mountain Unit 10-2 and 7-35L) to pits observed. Lines are not rigged up to the wells.

Blowdown line rigged up to Sheep Mountain Unit #8-2-P.

Unused equipment flowline laying behind compressor station NWNW128S70W compressor facility # 442259

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment flowline laying behind compressor station NWNW128S70W compressor facility # 442259		
Corrective Action:	Comply with Rule 606	Date:	07/31/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 211800 Type: WELL API Number: 055-06035 Status: PR Insp. Status: EG**Flowline**#1 Type: Dump Line 3 of LinesFlowline DescriptionFlowline Type: Dump Line Size: 2" Material: Carbon Steel

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. AbandonmentComment: Two unused flowline riser from wells (Sheep Mountain Unit 10-2 and 7-35L) to pits observed. Lines are not rigged up to the wells. Blowdown line rigged up to Sheep Mountain Unit #8-2-P.Corrective Action: Complete flowline abandonments to comply with Rule 1105. Remove all unused flowlines to blowdown pits on location.
30 Days to complete abandonments per 1105
24 hrs to OOSLAT;
OUT OF SERVICE LOCKS AND TAGS (OOSLAT) means locks and tags that an operator applies when equipment is in pre-commissioned status, is placed in an out of service status, or is in the process of abandonment. Out of service locks and tags must be visibly different from lock out and tag out devices used during repair or maintenance of the equipment.Date: 07/31/2023Facility ID: 211867 Type: WELL API Number: 055-06105 Status: PR Insp. Status: EGFacility ID: 211868 Type: WELL API Number: 055-06106 Status: PR Insp. Status: EG

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: 115231Lat: 37.646910Long: -105.179390Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Form 27 doc # 403348988Corrective Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Date: Type: BlowdownLined: NOPit ID: 483531Lat: 37.649030Long: -105.179790Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Form 27 doc# 403342341Corrective Date: **Fencing:**Fencing Type: WildlifeFencing Condition: AdequateComment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date:

Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard: <u>YES</u>
Comment:		
Corrective		
		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103765	Flowline integrity inspection 701103764 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6163813