

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Approximate area where the road is damaged marked in red. The damaged portion of the road is approximately 50 yards from Mamm Creek & is within NSO/High Priority/Density/Black Bear Habitat areas. It's also within close proximity to 411a Surface Water External buffer & Mamm Creek contributes directly to the Colorado River.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Photo # 1918 Damaged section of access road



Photo # 1920 Damage to access road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Photo # 1921 Damage to access road

Photo # 1924 Damaged section of access road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Photo # 1925 Damaged section of access road



Photo # 1927 Below access road in the creek bed/destabilization of area supporting access road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Photo # 1928 Below access road in the creek bed/destabilization of area supporting access road



Photo # 1929 Below access road in the creek bed/destabilization of area supporting access road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Photo # 1930 Below access road in the creek bed/destabilization of area supporting access road



Photo # 1931 Below access road in the creek bed/destabilization of area supporting access road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Photo # 1933 Below access road in the creek bed/destabilization of area supporting access road



Photo # 1937 Below access road in the creek bed/destabilization of area supporting access road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Photo # 1942 What appears to be heavy equipment tracks & dirt used to divert Mamm Creek



Photo # 1944 What appears to be heavy equipment tracks & dirt used to divert Mamm Creek

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Photo # 1946 What appears to be heavy equipment tracks & dirt used to divert Mamm Creek



Photo # 1947 What appears to be the new path of Mamm Creek & dirt brought in to divert it

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Photo # 1958 What appears to be the new path of Mamm Creek & dirt brought in to divert it



Photo # 1954 Dirt blocking path of creek & dry creek bed in the background

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Photo # 1955 Dirt blocking/diverting path of creek & dry creek bed

Photo # 1941 Dirt blocking/diverting path of creek & dry creek bed

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Photo # 1939 Dirt blocking/diverting path of creek & dry creek bed



Photo # 1938 Dry creek bed

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BRYNILDSON ACCESS ROAD



Photo # 1940 Dry creek bed



Photo # 1937 Dry creek bed & damage to slope supporting the access road in the background