

**Scout Energy Management LLC
A. C. McLaughlin 39A
Location #316423**



West entrance tracking pad installed since last inspection



East entrance tracking pad installed since last inspection

**Scout Energy Management LLC
A. C. McLaughlin 39A
Location #316423**



Location view from Southeast corner



Location view from Northeast corner

**Scout Energy Management LLC
A. C. McLaughlin 39A
Location #316423**



Location view from Northwest corner

Location view from Southwest corner