

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/24/2023

Submitted Date:

06/22/2023

Document Number:

701103750

**FIELD INSPECTION FORM**Loc ID 325606 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96735

Name of Operator: WILLIFORD RESOURCES LLC

Address: 6506 S LEWIS AVE STE 102

City: TULSA State: OK Zip: 74136

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Stevens, Glenn		glennstevens@centurylink.com	All SW Inspections
Williford, Hearne		hwilli@swbell.net	All SW field inspections
Devine, Ellice		ellice.devine@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215093	WELL	SI	02/01/2023	OW	067-06698	ANGELINA 4	EG

**General Comment:**

Flowline integrity inspection: Review of Form 44 (none found).

Flowlines not registered from wells (Angelina #4, 5, 6, 7, 8) to remote battery (Coordinates 37.1351 -108.09225) on County Road 129.

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Inspected Facilities**Facility ID: 215093 Type: WELL API Number: 067-06698 Status: SI Insp. Status: EG**Flowline**

#1	Type:	of Lines	
<u>Flowline Description</u>			
Flowline Type:	Size:	Material:	
Variance:	Age:	Contents: <u>Crude Oil</u>	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:	Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment			
Comment:	Flowlines not registered from wells (Angelina #4, 5, 6, 7, 8) to remote battery (Coordinates 37.1351 -108.09225) on County Road 129.		
Corrective Action:	Submit an Eform 44 Flowline Report per Rule 1101.d.		Date: <u>07/28/2023</u>

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403443078	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6158060">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6158060</a>
701103751	Flowline integrity inspection 701103750 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6158049">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6158049</a>
701103752	Map of Angelina #4, 5, 6, 7, 8 wells and remote battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6158050">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6158050</a>