

Inspection Photos
Location Name: FARM RANCH EXPLORATIONS#3
Location ID:320067



Photo# 1 Pump jack.



Photo# 2 Packing is leaking at well head.