

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2023

Submitted Date:

06/30/2023

Document Number:

690204385

**FIELD INSPECTION FORM**

Loc ID 324832 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 383 INVERNESS PKWY, STE 360  
City: ENGLEWOOD State: CO Zip: 80112

**Findings:**

- 9 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
BEAR STACY		stacy@strachanexploration.com	
HARMS JASON		jason@strachanexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213007	WELL	PR	08/14/1987	GW	061-06368	LAS ANIMAS 1-1	RI

**General Comment:**

On 6/29/2023, Ryan Costa conducted a location inspection. See attached photos and additional details within this report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	The battery sign is faded and too small to see and does not meet the signage requirements. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	06/29/2023
Type	BATTERY		
Comment:	The labeling on the tanks are faded and peeled off. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/29/2023

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Condensate	Tank		
Comment:	There was a dripping condensate leak at the offsite open top tank. Operator was notified the day of inspection for immediate repair.		
Corrective Action:	Immediately Control and contain spills/releases and clean up per Rule 912.a.	Date:	06/29/2023

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	The fence aournd the tanks is missing or inadeuate to prevent livestock entry. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	06/29/2023

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1		Open Top		38.438960,-103.062250
Comment:	The netting on the tank is torn and needs to be repaired. Operator was notified the day of inspection for immediate repair.				
Corrective Action:	Install or repair wildlife protection equipment.				Date: 06/29/2023

**Paint**

Condition:

Other (Content):

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate			Inadequate
Comment: <span style="color: blue;">The berm around the open top tank is insufficient to contain a spill. Corrective action is the day of inspection and the location will remain out of compliance until completed.</span>				
Corrective Action: <span style="color: red;">Repair or install berms or other secondary containment devices per Rule 603.o.</span>				Date: <u>06/29/2023</u>

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1		Open Top		38.438860,-103.069030

Comment: <span style="color: blue;">There is no netting to prevent wildlife entry of the open top tank at the wellsite. Operator was notified the day of inspection for immediate install.</span>				
Corrective Action: <span style="color: red;">Install or repair wildlife protection equipment.</span>				Date: <u>06/29/2023</u>

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth		Walls Insufficient		Inadequate
Comment: <span style="color: blue;">There are animal burroughsin the secondary containment berm which needs t be repaired. Corrective action is the day of inspection and the location will remain out of compliance until completed.</span>				
Corrective Action: <span style="color: red;">Repair or install berms or other secondary containment devices per Rule 603.o.</span>				Date: <u>06/29/2023</u>

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690204386	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6166682">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6166682</a>