

Inspection Photos

API: 061-06296

Operator: STRACHAN EXPLORATION INC

Inspection Date: 6/29/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06296 | Date: 6/29/2023

Inspection Photos



Photo 1. Facing southeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 6/29/2023

Inspection Photos



Photo 2. Facing toward the pumpjack. There are two barrel stored in containment with faded labeling.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 6/29/2023

Inspection Photos



Photo 3. There is oily fluid and sludge that is overtopping the containment and needs immediate cleaned up and disposal.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 6/29/2023

Inspection Photos



Photo 4. The fence around the tank battery is inadequate to prevent livestock entry and is not maintained. The berm around the tank has animal borrows and is compromised.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 6/29/2023

Inspection Photos



Photo 5. There is oily sludge that has overtopped the tank and berm. The berm is inadequate to contain a spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 6/29/2023

Inspection Photos



Photo 6. The netting on the open top tank is in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 6/29/2023

Inspection Photos



Photo 7. The fence around the tank battery is inadequate to prevent livestock entry and is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 6/29/2023