

Inspection Photos

API: 061-06365

Operator: STRACHAN EXPLORATION INC

Inspection Date: 6/29/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06365 | Date: 6/29/2023

Inspection Photos



Photo 1. Facing southwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 6/29/2023

Inspection Photos



Photo 2. The fence around the tank is inadequate to prevent livestock entry and is not maintained. The berm around the tank is insufficient to contain a spill (150% of tank capacity).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 6/29/2023

Inspection Photos



Photo 3. Facing at the backside of the open top tanks. The labeling on the tanks is missing and/or inadequate. The fence around the open top tank is inadequate to prevent livestock



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 6/29/2023

Inspection Photos



Photo 4. Facing toward the pumjack.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 6/29/2023

Inspection Photos



Photo 5. There is oily sludge that has spilt onto the ground that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 6/29/2023

Inspection Photos



Photo 6. There is no labeling or secondary containment at these two large volume tanks.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 6/29/2023

Inspection Photos



Photo 7. Facing at the north side of the location. The fence around the tank battery is inadequate to prevent livestock entry and is not maintained. Berm is insufficient to contain a spill (150% of tank capacity).



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06365 | Date: 6/29/2023