

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2023

Submitted Date:

06/30/2023

Document Number:

705000349

## FIELD INSPECTION FORM

Loc ID 331615 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name       | Phone | Email                         | Comment |
|--------------------|-------|-------------------------------|---------|
| Schlagenhauf, Mark |       | mark.schlagenhauf@state.co.us |         |
|                    |       | COGCCInspections@Oxy.com      |         |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|-----------------|-------------|
| 331615      | LOCATION | AC     |             |            | -         | HOWARD 25C-22HZ | EG          |
| 434532      | WELL     | PR     | 04/27/2014  | OW         | 123-38231 | HOWARD 25C-22HZ | PA          |

**General Comment:**

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)  
[Photos uploaded](#)

**Inspected Facilities**

Facility ID: 331615 Type: LOCATION API Number: - Status: AC Insp. Status: EG

Facility ID: 434532 Type: WELL API Number: 123-38231 Status: PR Insp. Status: PA

**Flowline**

|    |                     |          |
|----|---------------------|----------|
| #1 | Type: Non-Well Site | of Lines |
|----|---------------------|----------|

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Well (Howard 25C-22HZ) has been plugged and abandoned. COGCC form 42 notice of start of plugging operations received 3/2023. Fenced excavation observed at the PA wellhead; flowline riser (WH OLF) at PA well has been removed. Fenced excavation observed at HHS; flowline end is disconnected/ isolated (OOSLAT/ blind flange). Facility/ battery services additional (PR) wells. Remediation work is in progress (WH/ historical).

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <span style="color: blue;">As outlined on COGCC form 19 spill report Doc #403439853 received on 06/21/2023: On June 20, 2023, historically impacted soil was discovered during cut and cap operations at the Howard 25C-22HZX wellhead. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.</span> | maclarej | 06/30/2023 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---|---|
| 705000356    | Fenced excavation at PA well; FL riser removed      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6167033">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6167033</a> |
| 705000357    | Signage at tank battery                             | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6167034">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6167034</a> |
| 705000358    | Fenced excavation at HHS; FL isolated/ disconnected | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6167035">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6167035</a> |