

Inspection Photos

API: 061-06459

Operator: STRACHAN EXPLORATION INC

Inspection Date: 6/29/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06459 | Date: 6/29/2023

Inspection Photos



Photo 1. Facing toward the offsite tank battery.



Inspection Photos



Photo 2. The fence around the tank is inadequate to prevent livestock entry and is not maintained. The berm around the tank is insufficient to contain a spill (150% of tank capacity) and has animal borroughs the sides.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06459 | Date: 6/29/2023

Inspection Photos



Photo 3. There is stained soils that need to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06459 | Date: 6/29/2023

Inspection Photos



Photo 4. There is unused disconnected pipe that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06459 | Date: 6/29/2023

Inspection Photos



Photo 5. This tank is not in use and needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06459 | Date: 6/29/2023

Inspection Photos



Photo 6. Facing toward the wellsite. There is no sign posted at the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06459 | Date: 6/29/2023

Inspection Photos



Photo 7. There is unused pipe and cable that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06459 | Date: 6/29/2023

Inspection Photos



Photo 8. There is oily fluid in the containment next to the pump jack. Oily fluid has spilled onto the ground and needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06459 | Date: 6/29/2023