

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2023

Submitted Date:

06/28/2023

Document Number:

702402040

FIELD INSPECTION FORMLoc ID 333138 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240805	WELL	PR	02/01/2023	OW	123-08593	RASMUSSEN 1	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type			
Comment:	See Inspection Doc # 702400616 for related shared facilities and equipment.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	unused pump jack broken down on location and weeds are beginning to grow around it.		
Corrective Action:	Comply with Rule 606 unused equipment	Date:	05/17/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	See Inspection Doc # 702400616 for related shared facilities and equipment		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

Equipment:

Type:	#		corrective date
Comment:	See Inspection Doc # 702400616 for related shared facilities and equipment		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	partially exposed at surface	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:	unused	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	See Inspection Doc # 702400616 for related shared facilities and equipment					
Corrective Action:						Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	240805	Type:	WELL	API Number:	123-08593	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="SI"/>									
Corrective Action: <input type="text"/> Date: _____									
BradenHead									
Date of Last Brhd Test: <input type="text" value="05/23/2023"/> Annual Brhd Completed? <input type="text" value="Yes"/>									
Last Brhd Test Results Initial Surf Csg Pressure: <input type="text" value="0"/> Fluid Type: _____									
End Surf Csg Pressure: <input type="text" value="0"/>									
Comment: <input type="text"/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 6-28-2023 at approximately 1315 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to FIR Doc # 702401842</p> <p>Operator: KP Kauffman</p> <p>Location name: Rasmussen 1</p> <p>API #05-123-08593</p> <p>County: Weld</p> <p>Weather: Clear/Hot.</p> <p>Location: Dry.</p> <p>While there, I observed a wellsite, SI at the time of inspection.</p> <p>During this inspection, I observed the following possible compliance issue and it is now delinquent:</p> <p>606 unused Equipment: unused pump jack on location, CA date 5-17-2023.</p> <p>See attached photos.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	06/28/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403448853	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6164318
702402041	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6164314